

Project:	Operative Plant Operations with Limited Vision	RA No:	33	Review Date
Operation / Task:	Operative Plant Operations with Limited Vision	Persons at risk:	All employees and Visitors	31/01/2027
Location / Area:	All L Lynch Depots Workshop/Yard	Public at risk:	No	
Monitoring Responsibility:	HSQE Team, Plant Service Manager, Compliance Manager, Workshop Foreman, Depot Manager			

KEY

S = Severity Rating

1. Negligible
2. Minor Injury
3. Major Injury (RIDDOR)
4. Fatality
5. Multiple Fatality

L = Likelihood of Occurrence

1. Improbable
2. Remote 1 – 10%
3. Possible 10 – 50%
4. Probable 50 – 90%
5. Almost certain 90%+

RR = Risk Rating

Severity	5	10	15	20	25
4	4	8	12	16	20
3	3	6	9	12	15
2	2	4	6	8	10
1	1	2	3	4	5
	Likelihood				

R Unacceptable risk, plan out or add further controls.
O Acceptable only if no other method viable & with high level controls in place.
Y Acceptable with suitable controls.
G Acceptable, no further action required.

Activity	Hazards/Risks Identified	Risk Rating			Control Measures	Residual Risk			Responsibility
		S	L	RR		S	L	RR	
Operating plant by operators with limited vision	Lack of PPE Incorrect or unsuitable PPE Misuse of PPE Limited field of vision Slips, trips and falls. Working near other site activities. Night-time vision Working without sight	4	4	16	<ul style="list-style-type: none"> All Operatives Must wear correctly fitting PPE. Full PPE must be worn during spent time on all sites and depots. Brother Keeper and check each other's PPE. Anyone without PPE should contact the site Supervisor prior to carrying on with the task. The operator must report any defective mirrors or in cab camera technology immediately and not operate until the item of plant until defects have been rectified. The operative must have a very good field of vision in the other remaining good eye. The operative must have the eye tested every year to ensure no change in the vision. A Eye Sight Check will be taken by Lynch Project Manager ONLY CPCS card holders are able to operate only plant identified on the back of their CSCS Card. The Operative must have another operative / aid with him at all times during the shift to ensure all hazards are pointed out. Operative should be working within the safe zone at ALL times 	4	2	8	HSQE Team Plant Service Manager. On Site Service Engineer. Plant Service Foreman. Compliance Manager Workshop Foreman Depot Manager

Project:	Operative Plant Operations with Limited Vision	RA No:	33	Review Date 31/01/2027
Operation / Task:	Operative Plant Operations with Limited Vision	Persons at risk:	All employees and Visitors	
Location / Area:	All L Lynch Depots Workshop/Yard	Public at risk:	No	
Monitoring Responsibility:	HSQE Team, Plant Service Manager, Compliance Manager, Workshop Foreman, Depot Manager			

KEY

S = Severity Rating

L = Likelihood of Occurrence

RR = Risk Rating

Severity	5	10	15	20	25
4	4	8	12	16	20
3	3	6	9	12	15
2	2	4	6	8	10
1	1	2	3	4	5
	1	2	3	4	5
	Likelihood				

R Unacceptable risk, plan out or add further controls.
O Acceptable only if no other method viable & with high level controls in place.
Y Acceptable with suitable controls.
G Acceptable, no further action required.

Risk Assessment Prepared By: Paul Lynch **Signature:** **Date:** 31/01/2026

Risk Assessment Reviewed By: Daniela Rizvan **Signature:** **Date:** 31/01/2026

