


<b>Project:</b>	Lynch Depots	<b>RA No:</b>	68	<b>Review Date</b>
<b>Operation / Task:</b>	Cab Cleaning + Use of Machines	<b>Persons at risk:</b>	Operators, Cab Cleaners	<b>31/01/2027</b>
<b>Location / Area:</b>	Workshop/Yard/Site	<b>Public at risk:</b>	No	
<b>Monitoring Responsibility:</b>	HSQE Team, Workshop Department Managers/Supervisors, All workshop and yard staff.			

**KEY**

**S = Severity Rating**

**L = Likelihood of Occurrence**

**RR = Risk Rating**



1. Negligible	1. Improbable	5	5	10	15	20	25	<b>R</b> Unacceptable risk, plan out or add further controls. <b>O</b> Acceptable only if no other method viable & with high level controls in place. <b>Y</b> Acceptable with suitable controls. <b>G</b> Acceptable, no further action required.
2. Minor Injury	2. Remote 1 – 10%	4	4	8	12	16	20	
3. Major Injury (RIDDOR)	3. Possible 10 – 50%	3	3	6	9	12	15	
4. Fatality	4. Probable 50 – 90%	2	2	4	6	8	10	
5. Multiple Fatality	5. Almost certain 90%+	1	1	2	3	4	5	

Likelihood

Activity	Hazards/Risks Identified	Risk Rating			Control Measures	Residual Risk			Responsibility
		S	L	RR		S	L	RR	
This assessment will consider the use and cleaning of all machine cabs	Contact with a sharp object puncture i.e.: used needle, broken glass, blade, Exposure to blood-borne viruses (BBV's) and hepatitis C or B (HCV), HIV the virus that causes AIDS and bacteria such as staph	4	3	12	<ul style="list-style-type: none"> <li>Operatives to ensure all machines are left clean and tidy after use and any personal belongings are taken out of the machine</li> <li>All operatives including cab cleaners must always look for sharps hazards i.e.: sharp objects - broken glass, needles prior use or cleaning of any machine cabs.</li> <li>Operatives and cleaners to report to their line manager or supervisor in charge immediately on discovering any needles/syringes.</li> <li>All sharps/sharp objects to be removed from the machine cabs, with the use of cut- resistance gloves (EN388) or mechanical picker when handling the all sharps.</li> <li>All sharps (needles/syringes) must be disposed of in a sealed sharps container and disposed of by a licensed contractor.</li> <li>All Lynch staff must contact a Lynch First aider for a medical treatment and act on a medical advice given.</li> <li>HQSE Team must be informed and a full investigation conducted and recorded.</li> <li>Cab cleaners are not permitted to operate any plant item without completing required competencies. i.e., plant mover in each item of plant type.</li> <li>Cab cleaners must attend a full H+S induction ensuring that depot hazards are briefed and understood.</li> </ul>	4	2	8	HSQE Team Workshop manager, Supervisor, Foreman.

<b>Project:</b>	Lynch Depots	<b>RA No:</b>	68	<b>Review Date</b>
<b>Operation / Task:</b>	Cab Cleaning + Use of Machines	<b>Persons at risk:</b>	Operators, Cab Cleaners	<b>31/01/2027</b>
<b>Location / Area:</b>	Workshop/Yard/Site	<b>Public at risk:</b>	No	
<b>Monitoring Responsibility:</b>	HSQE Team, Workshop Department Managers/Supervisors, All workshop and yard staff.			

**KEY**

**S = Severity Rating**

**L = Likelihood of Occurrence**

1. Negligible
2. Minor Injury
3. Major Injury (RIDDOR)
4. Fatality
5. Multiple Fatality

**L = Likelihood of Occurrence**

1. Improbable
2. Remote 1 – 10%
3. Possible 10 – 50%
4. Probable 50 – 90%
5. Almost certain 90%+

**RR = Risk Rating**

Severity	5	4	3	2	1
5	5	10	15	20	25
4	4	8	12	16	20
3	3	6	9	12	15
2	2	4	6	8	10
1	1	2	3	4	5
	1	2	3	4	5

Likelihood

**Risk Rating Legend:**

- R** Unacceptable risk, plan out or add further controls.
- O** Acceptable only if no other method viable & with high level controls in place.
- Y** Acceptable with suitable controls.
- G** Acceptable, no further action required.

<b>Risk Assessment Prepared By:</b>	Paul Lynch	<b>Signature:</b>		<b>Date:</b>	31/01/2026
<b>Risk Assessment Reviewed By:</b>	Daniela Rizvan	<b>Signature:</b>		<b>Date:</b>	31/01/2026